

**RENAULT** X40

**SIDE COLLISION**

**MOUNTINGS MAKING UP THE DOORS**

**BASIC MANUAL: M.R. 258**  
**CHAPTER: SIDE COLLISION**

**TECHNICAL  
NOTE**



**116**

September 1987  
EDITION ANGLAISE

Service 0422

RENAULT  
**5**

#### **1 - CAUSE**

Difficulty in positioning all the door trim fastenings correctly and dismantling-reassembly method.

#### **2 - RISK**

Incorrect assembly.

#### **3 - METHODS SOLUTION**


3.1 Diagram illustrating the securing points.

3.2 Details of various fastenings and whether or not they can be recovered.

3.3 Method of dismantling fastenings which can be recovered.

#### **4 - METHODS ADVICE**

Use tool D 115 to unpick the trims fastened with clips (of the pressure stud type).






**T1** ● 77 03 077 193

Cloth trim (2 doors)  
Plastic trim (4 doors)



**T** \* 77 03 077 022



**T2** ● 77 03 077 228

Plastic trim (2 doors)



**A** 12 ● 77 03 077 192




**B** \* 77 03 081 076




77 03 079 290



**D** \* 77 03 081 019



**E** 19 ● 77 03 077 109




77 03 016 475



77 03 016 471



77 03 016 470



77 03 085 037




77 03 044 037  
Ø 6 mm dia.





77 03 079 347






\* destroyed on removal

● Fastenings which can be recovered are dismantled using tool D.115.



83614





\* destroyed on removal

● Fastenings which can be recovered are dismantled using tool D.115.

